## APPENDIX A

Well Gauging Reports and Field Reports

## PETROLEUM PRODUCT / WATER - LEVEL DATA SHEET

W.O. #: 2781

PROJECT: Chester River Hospital Center LOCATION: Chestertown, Maryland

DATE: 1-Oct-12
WEATHER: 70 F
COLLECTED BY: TL, TT
ENTERED BY: TL

	Chestertown, Mar						ENTERED BY:	
Type produ Petro corre		Fuel oil 0.80						
Monitoring Point	Description of Measuring Point (It msl)	Measuring Point Elevation (It)	Product Depth (ft)	Water Depth (ft)	Product Thickness (ft)	Fluid Level Elevation (ft msl)	Corrected Water Elevation (ft msl)	Estimated Amount Product Recovered (gat) / NOTES:
MW-1	Lip of Casing	57.05		46.11		10.94	10.94	
MW-2	Lip of Casing	56.37		45.52		10.85	10.85	
MW-3	Lip of Casing	50.55		39.95		10.60	10.60	
MW-4	Lip of Casing	53.4		36.68		16.72	16.72	
MW-5	Lip of Casing	61.08		50.10		10.98	10.98	
MW-6	Lip of Casing						*********	Well destroyed in building expansion
MW-7	Lip of Casing							Well destroyed in building expansion
MW-8	Lip of Casing	47.6		37.55		10.05	10.05	
MW-9	Lip of Casing	46.95		37.09		9.86	9.86	
MW-10	Lip of Casing	47.76		37.66		10.10	10.10	
MW-11	Lip of Casing	41.49		32.09		9.40	9.40	
MW-12	Lip of Casing	44.46		34.60		9.86	9.86	
MW-13	Lip of Casing	41.7		32.49		9.21	9.21	
MW-14	Lip of Casing	41.38	32.16	32.16	0.00	9.22	9.22	sheen
MW-15	Lip of Casing	35.01		26.79		8.22	8.22	sampled
MW-16	Lip of Casing	35.55		27.35		8.20	8.20	sampled
MW-17	Lip of Casing	35.49		27.27		8.22	8.22	
MW-18	Lip of Casing	35.82		28.54		7.28	7.28	
MW-19	Lip of Casing	38.85		30.00		8.85	8.85	sampled
MW-20	Lip of Casing	38.72		29.84		8.88	8.88	sampled; sheen observed in sample after purging well
MW-21	Lip of Casing	38.55		29.68		8.87	8.87	
MW-22	Lip of Casing	45.75	35.94	35.94	0.00	9.81	9.81	sheen
MW-23	Lip of Casing	35.95		28.64		7.31	7.31	
MW-24	Lip of Casing	36.56		28.41		8.15	8.15	sampled
MW-25	Lip of Casing	36.1		28.27		7.83	7.83	
MW-27	Lip of Casing							well abandoned
MW-28	Lip of Casing	35.9		28.31		7.59	7.59	
MW-29	Lip of Casing	35.15		28.27		6.88	6.88	
MW-30	Lip of Casing							Well destroyed in building expansion
MW-31	Lip of Casing	46.31		36.28		10.03	10.03	
MW-32	Lip of Casing	44.6		34.95		9.65	9.65	
MW-33	Lip of Casing	36.52		27.94		8.58	8.58	sampled
MW-34	Lip of Casing	36.64		28.08		8.56	8.56	sampled
MW-35	Lip of Casing	38.62		29.70		8.92	8.92	sampled
MW-37	Lip of Casing	50,54	39.90	39.90	0.00	10.64	10,64	film
MW-38	Lip of Casing							pump stuck in well - not able to gauge
RW-1B	Lip of Casing	45.96		35.90		10.06	10.06	
RW-20	Lip of Casing	40.54	31.28	31.28	0.00	9.26	9.26	film
RW-3B	Lip of Casing	39.45	30.24	30.24	0.00	9.21	9.21	sheen
MW-40	Lip of Casing	46.85		35.88		9.97	9.97	
MW-41	Lip of Casing	42.92		33.37		9.55	9.55	
RW-4	Lip of Casing	45.69		35.74		9.95	9.95	
RW-5	Lip of Casing	43.34	33,60	33.60	0.00	9.74	9.74	sheen
RW-6	Lip of Casing	47.22		37.04		10.18	10.18	
RW-2A	Lip of Casing	39.84		*******				well abandoned 3-08
RW-28	Lip of Casing	39.18			******			well abandoned 3-08
RW-2C	Lip of Casing	******					*******	well abandoned 9-03
RW-3A	Lip of Casing							well abandoned 9-03
MW-42	Lip of Casing	47.04		37.10		9.94	9,94	
MW-43	Lip of Casing	46.55	36.70	36.70	0.00	9.85	9.85	sheen
MW-44	Lip of Casing	46.66		36.86		9.80	9.80	
MW-45	Lip of Casing	40.91		31.69		9.22	9.22	
MW-46	Lip of Casing	41.08	31.84	31.84	0.00	9.24	9.24	sheen
MW-47	Lip of Casing	40.74	31.49	31.58	0.09	9.25	9.23	used absorbent wic to recover 0.05 gal of free product; film remaining
W-1	Lip of Casing			36.68				

Project Name:	Chester River Hospita	Center	··	Dat	9:		1-Oct-12
Project #:	2781		······································	Tim	e on	- site	:11:05 AM
Location:	Chestertown, Marylan	d		We	ather	:	70 F
Personnel preser	t at site: TL, TT			Veh	icle:		98 Ranger
Reason for site	visit:	yes	no		•		
Surveying			Ø	1			
Monitoring							
Sampling		7		7			
Other		$\subseteq$		1			
Recovery system	maintenance		<b>4</b>	1			
Recovery system			V	1			
Scheduled							
Activities	Checklist			yes	no	n/a	Exceptions (with explanation and comments)
	Measured water & petro		S	Time on - site: 11:05 AM  Weather: 70 F  Vehicle: 98 Ranger  yes no n/a Exceptions (with explanation and comments) all wells  yes no n/a Exceptions (with explanation and comments)  where no n/a Exceptions (with explanation and comment			
	Pumped petroleum from	wells			Ø		
Routine	Emptied petro trap					Ø	
Monitoring	Installed, replaced, or in	,		v			Used wic to recover product from MW-47 and removed wic before leaving site
	Measured and recorded	system da	ata			Ø	
	Surveyed well elevation	S				V	
	Inspected system discha	arge at sto	rm drain			Ø	
	Groundwater sampling(i were sampled on petro		wells	V			MW-15, MW-16, MW-19, MW-20, MW-24, MW-33, MW-34 a MW-35
	Petroleum sampling(not were sampled on petro	e which we	ells		Ø		
Sampling	Soil sampling					Ø	
-	Vapor system sampling					V	
	Collected sample(s) in Is	ab bottle(s	) & chilled	V			
	Filled out labels and cha	in-of-custo	ody	Ø			
	Recorded amount recov	ered				V	
Other	Completed site sketch					Ø	
Activities	Recovery system repair				V		
	Completed materials an	a equipme	nt form	V			
Comments Observations	Sampled eig MW-35 Used an abs	vells as pa ht wells as orbent wic	rt of monthly part of mon to recover	y mor nthly appro	moni x. 0.	toring 05 ga	

## PETROLEUM PRODUCT / WATER - LEVEL DAYA SHEET

W.O. #: 2781

PROJECT: Chester River Hospital Center LOCATION: Chestertown, Maryland

DATE: 5-Nov-2012
WEATHER: 35 F
COLLECTED BY: TL, TT
ENTERED BY: TL

LOCATION:	Chestertown, Mar	yland					ENTERED BY:	TL
Type produ	rct: ction factor:	Fuel oil 0.80						
Monitoring Point	Description of Measuring Point (ft msl)	Measuring Point Elevation (ft)	Product Depth (ft)	Water Depth (ft)	Product Thickness (ft)	Fluid Level Elevation (ft msl)	Corrected Water Elevation (ft msi)	Estimated Amount Product Recovered (gal) / NOTES:
MW-1	Lip of Casing	57.05		46.24	``	10,81	10.81	
MW-2	Lip of Casing	56.37		45.63		10.74	10.74	
MW-3	Lip of Casing	50.55		40.05		10.50	10.50	
MW-4	Lip of Casing	53.4		42.75		10.65	10.65	
MW-5	Lip of Casing	61.08		50.23		10.85	10.85	
MW-6	Lip of Casing							Well destroyed in building expansion Nov 2000
MW-7	Lip of Casing				,			Wetl destroyed in building expansion Nov 2000
MW-8	Lip of Casing	47.6		37.52		10.08	10.08	
MW-9	Lip of Casing			36.33				
MW-10	Lip of Casing	47.76						Not gauged - under construction equipment
MW-11	Lip of Casing	41.49		32.17		9.32	9.32	
MW-12	Lip of Casing	44.46		34.68		9.78	9.78	
MW-13	Lip of Casing	41.7	22.02	32.59	2.00	9.11	9.11	
MW-14	Lip of Casing	41.38	32.22	32.22	0.00	9.16	9.16	sheen
MW-15 MW-16	Lip of Casing	35.01 35.55		26.82 27.40		8.19 8.15	8.19 8.15	sampled
MW-17	Lip of Casing Lip of Casing	35.49		27.32		8.17	8.17	sampled
MW-18	Lip of Casing	35.82		28.55		7.27	7.27	
MW-19	Lip of Casing	38.85		30.07		8.78	8.78	sampled
MW-20	Lip of Casing	38.72		29.92		8.80	8.80	sampled
MW-21	Lip of Casing	38.55		29.74		8.81	8.81	
MW-22	Lip of Casing	45.75	36.03	36.03	0.00	9.72	9.72	sheen
MW-23	Lip of Casing	35.95		28.65		7.30	7.30	
MW-24	Lip of Casing	36.56		28.48		8.08	8.08	sampled
MW-25	Lip of Casing	36.1		28.31		7.79	7.79	
MW-27	Lip of Casing							Well abandoned Nov 2006
MW-28	Lip of Casing	35.9		28.31		7.59	7.59	
MW-29	Lip of Casing	35.15		28.24		6.91	6.91	
MW-30	Lip of Casing							Well destroyed in building expansion Nov 2000
MW-31	Lip of Casing	46.31						Not gauged - under construction equipment
MW-32	Lip of Casing	44.6						Not gauged - under construction equipment
MW-33	Lip of Casing	36.52		27.99		8.53	8.53	sampled
MW-34	Lip of Casing	36.64		28.14		8.50	8.50	sampled
MW-35	Lip of Casing	38.62		29.72		8.90	8.90	sampled
MW-37	Lip of Casing	50.54	40.00	40.00	0.00	10.54	10.54	film
MW-38 RW-1B	Lip of Casing Lip of Casing	46.71	36.70	36.70	0.00	10.01	10.01	pump stuck in well - not able to gauge sheen
RW-2D	Lip of Casing	40.71	31.34	31.36	0.02	9.20	9.20	recovered product using an absorbent wic
RW-3B	Lip of Casing	39.45	30.32	30.32	0.00	9.13	9.13	film
MW-40	Lip of Casing	46.85	36,98	36.98	0.00	9.87	9.87	sheen
MW-41	Lip of Casing	42.92	33.43	33.43	0.00	9.49	9.49	sheen
RW-4	Lip of Casing	45.69	35.84	35.84	0.00	9.85	9.85	sheen
RW-5	Lip of Casing	43.34	33.67	33.67	0.00	9.67	9.67	sheen
RW-6	Lip of Casing	47.22		37.14		10.08	10.08	
RW-2A	Lip of Casing	39.84					*******	Well abandoned Mar 2008
RW-2B	Lip of Casing	39.18						Well abandoned Mar 2008
RW-2C	Lip of Casing						*****	Well abandoned Sep 2003
RW-3A	Lip of Casing							Well abandoned Sep 2003
MW-42	Lip of Casing			36.30				
MW-43	Lip of Casing	46.55		36.78		9,77	9.77	
MW-44	Lip of Casing	46,66		36.97		9,69	9,69	
MW-45	Lip of Casing	40.91		31.78		9.13	9,13	
MW-46	Lip of Casing	41.08	31.93	31.93	0.00	9.15	9.15	sheen
MW-47	Lip of Casing	40.74						Not gauged - under construction equipment
IW-1	Lip of Casing			36.76				

Project Name:	Chester River Hospita	l Center		Date	э;		5-Nov-12			
Project #:	2781			Tim	e on	- site	8:00 AM			
Location:	Chestertown, Marylan	d		Wea	ather	:	35 F			
Personnel present at site: TL, TT							98 Ranger			
Reason for site s Surveying Monitoring	yes	no -								
Sampling Other										
Recovery system	maintenance		V.	1						
Recovery system	<del></del>	Ш	4							
Scheduled										
Activities	Checklist			yes	no	n/a				
	Measured water & petro	oleum leveis								
	Pumped petroleum from	n wells			V					
Routine	Emptied petro trap					Ø				
Monitoring	Installed, replaced, or in						Used wic to recover product from RW-2D and removed wic before leaving site			
	Measured and recorded	•	ta			Ø				
	Surveyed well elevation					V				
Inspected system discharge at storm drain						Ø				
	Groundwater sampling( were sampled on petro	form)		Ø			MW-15, MW-16, MW-19, MW-20, MW-24, MW-33, MW-34 a MW-35			
	Petroleum sampling(not were sampled on petro		lls		Ø					
Sampling	Soil sampling					Ø				
, ,	Vapor system sampling					Ø				
	Collected sample(s) in I	ab bottle(s)	& chilled	Ø						
	Filled out labels and cha	ain-of-custo	dy	V						
	Recorded amount recov	rered				V				
Other	Completed site sketch					V				
Activities	Recovery system repair				Ø					
	Completed materials an	d equipmen	t form	Ø						
Comments Observations	MW-35	vells as part tht wells as sorbent wic	g: MW-15, MW-16, MW-19, MW-20, MW-24, MW-33, MW-34 free product from RW-2D; removed wic from well before leavin							

## PETROLEUM PRODUCT / WATER - LEVEL DATA SHEET

W.O. #: 2781

PROJECT: Chester River Hospital Center LOCATION: Chestertown, Maryland

DATE: 4-Dec-2012
WEATHER: 55 F
COLLECTED BY: 7L, TT
ENTERED BY: TL

Type product: Fuel oil Petro correction factor: 0.80									
(649) VSS	Description of	Measuring Point	Product	Water	Product	Fluid	Corrected	Estimated Amount	
Monitoring Point	Measuring Point (ft msl)	Elevation (ft)	Depth (ft)	Depth (ft)	Thickness (N)	Level Elevation (ft mst)	Water Elevation (ft msl)	Product Recovered (gal) / NOTES:	
MW-1	Lip of Casing	57.05	46.12	46.12	0.00	10.93	10.93	sheen; sampled (sheen in sample)	
MW-2	Lip of Casing	56.37		45.55		10.82	10.82	sampled (sheen in sample)	
MW-3	Lip of Casing	50.55	39.92	39.92	0.00	10.63	10.63	sheen; sampled (sheen in sample)	
MW-4	Lip of Casing	53.4		42.64		10.76	10.76	sampled	
MW-5	Lip of Casing	61.08		50.12		10.96	10.96	sampled	
MW-6	Lip of Casing							Well destroyed in building expansion Nov 2000	
MW-7	Lip of Casing	*******						Well destroyed in building expansion Nov 2000	
MW-8	Lip of Casing	47.6		37.51		10.09	10.09	sampled	
MW-9	Lip of Casing			36.18				sampled (sheen in sample)	
MW-10	Lip of Casing							Well abandoned Nov 2012	
MW-10R	Lip of Casing	14.40		36.90		0.54	0.54	Well installed Nov 2012; sampled	
MW-11	Lip of Casing Lip of Casing	41.49		31.98		9.51	9.51	sampled	
MW-12 MW-13	Lip of Casing Lip of Casing	44.46 41.7		34,53		9.93	9.93	sampled	
MW-14	Lip of Casing	41.7	32.04	32.41 32.04	0.00	9.29 9.34	9.29 9.34	sampled  film; sampled (free product film in sample)	
MW-14 MW-15	Lip of Casing Lip of Casing	35.01	32.04	26.63	0.00	8.38	8.38	nim; sampled (ree product nim in sample)	
MW-16	Lip of Casing Lip of Casing	35.55		27.19		8.36	8.36	sampled sampled	
MW-17	Lip of Casing	35.49		27.10	<b></b>	8.39	8,39	sampled	
MW-18	Lip of Casing	35.82		28.30		7,52	7.52	sampled	
MW-19	Lip of Casing	38.85		29.89		8.96	8.96	sampled	
MW-20	Lip of Casing	38.72		29.72		9.00	9.00	sampled	
MW-21	Lip of Casing	38.55		29.56		8.99	8,99	sampled	
MW-22	Lip of Casing	45.75	35.88	35.88	0.00	9.87	9.87	sheen; sampled on 5-Dec-12	
MW-23	Lip of Casing	35,95		28.40		7.55	7.55	sampled	
MW-24	Lip of Casing	36.56		28.28		8.28	8.28	sampled	
MW-25	Lip of Casing	36.1		28.08		8.02	8.02	sampled	
MW-27	Lip of Casing							Well abandoned Nov 2006	
MW-28	Lip of Casing	35.9		28.02		7.88	7.88	sampled	
MW-29	Lip of Casing	35.15		27.96		7,19	7.19	sampled	
MW-30	Lip of Casing							Well destroyed in building expansion Nov 2000	
MW-31	Lip of Casing							Well abandoned Nov 2012	
MW-31R	Lip of Casing			36.19				Well installed Nov 2012; sampled	
MW-32	Lip of Casing	44.6		34.89		9.71	9.71	sampled	
MW-33	Lip of Casing	36.52		27.80		8.72	8.72	sampled	
MW-34	Lip of Casing	36.64		27.95		8.69	8.69	sampled	
MW-35	Lip of Casing	38.62		29.60		9.02	9.02	sampled	
MW-37	Lip of Casing	50.54	39.89	39.89	0.00	10.65	10.65	film; sampled (sheen in sample)	
MW-38	Lip of Casing						*****	pump stuck in well - not able to gauge	
RW-1B	Lip of Casing	46.71		36.58		10.13	10.13	sampled on 5-Dec-12	
RW-2D	Lip of Casing	40.54	31.18	31,18	0.00	9.36	9.36	film; sampled on 5-Dec-12	
RW-3B	Lip of Casing	39.45	31.14	31.14	0.00	8.31	8.31	film; sampled on 5-Dec-12 (free product film in sample)	
MW-40	Lip of Casing	46.85		36.84		10.01	10.01	sampled (film in sample)	
MW-41	Lip of Casing	42.92	33.29	33.29	0.00	9.63	9.63	sheen; sampled (sheen in sample)	
RW-4	Lip of Casing	45.69	35.68	35.68	0.00	10.01	10.01	sheen; sampled on 5-Dec-12 (sheen in sample)	
RW-5	Lip of Casing	43.34	33.52	33.52	0.00	9.82	9.82	film; sampled on 5-Dec-12 (sheen in sample)	
RW-6	Lip of Casing	47.22		37.01		10.21	10.21	sampled on 5-Dec-12	
RW-2A RW-2B	Lip of Casing	39.84					*******	Well abandoned Mar 2008	
RW-2B	Lip of Casing Lip of Casing	39.18			*******	*******	*******	Well abandoned Mar 2008 Well abandoned Sep 2003	
RW-3A MW-42	Lip of Casing			36 17				Well abandoned Sep 2003	
MW-43	Lip of Casing Lip of Casing	16 EE		36.17		0.04	0.04	sampled	
	Lip of Casing Lip of Casing	46.55		36.61 36.79		9.94	9.94 9.87	sampled	
MW-44 MW-45	Lip of Casing Lip of Casing	46.66 40.91		31.60		9.87	9.87 9.31	sampled sampled	
MW-45 MW-46			31.70	31.50	0.00	9.31	1		
MW-46 MW-47	Lip of Casing Lip of Casing	41.08 40.74	31.76 31.42	31.76	0.00	9.32 9.32	9.32 9.32	film; sampled film; sampled (sheen in sample)	
IW-1		40.74	31.44	36.61	0.00	9.32			
31-1	Lip of Casing			30.01				sampled	

Project Name:	Chester River Hospita	l Center		Date	<b>Э</b> :		4-Dec-2012
Project #:	2781			Tim	e on	- site	8:00 AM
Location:	Chestertown, Marylan	d		Wea	ather		55 F
Personnel presen	it at site: TL, TT, MW	, JPS		Veh	icle:		98 Ranger, 05 F-250, Van
Reason for site v	visit:	yes	no				
Surveying			<b>▽</b>				
Monitoring		<u> </u>					
Sampling		~					
Other			7				
Recovery system	maintenance		<b>V</b>	]			
Recovery system	repair		7				
Scheduled							
Activities	Checklist			yes	no	n/a	Exceptions (with explanation and comments)
	Measured water & petro			v			all wells
	Pumped petroleum from	wells			Ø		
Routine	Emptied petro trap					V	
Monitoring	Installed, replaced, or in	·			Ø		
	Measured and recorded	system dat	la			V	
	Surveyed well elevation	S				V	
	Inspected system disch	arge at stor	m drain			V	
·	Groundwater sampling(i were sampled on petro	form)		V		\( \sqrt{1}	all 39 monitoring wells on 4-Dec-2012 all 7 system wells on 5-Dec-2012
	Petroleum sampling(not were sampled on petro		ls		Ø		
Sampling	Soil sampling					Ø	
	Vapor system sampling					Ø	
	Collected sample(s) in la	ab bottle(s)	& chilled	V			
	Filled out labels and cha		dy	V			
	Recorded amount recov	ered				Ø	
Other	Completed site sketch					V	
Activities	Recovery system repair				V		
	Completed materials an	d equipmen	t form	V			
Comments Observations	System is of Gauged all v Quarterly sa 5-Dec-2012)	vells as part mpling of al	of monthly	/ mor	nitorir	ng g well	is sampled on 4-Dec-2012 and 7 system wells sampled on